



Photo 1 – View of damaged right wing lift strut, fuselage, and empennage (Photo courtesy of the FAA)