



Photo 1 – View of damaged empennage from rear (Photo courtesy of the FAA)