



Photo 1 – View of damaged right wing leading edge (Photo courtesy of the operator)



Photo 2 – View of damaged spar (Photo courtesy of the operator)