



Photo 1 – View of damage to the forward right fuselage bulkhead assembly and stringer assembly (Courtesy of FAA)