



Photo 1 – View of damage to both wings (Courtesy of FAA)



Photo 2 – View of carburetor heat position indicator (Courtesy of FAA)