



Photo 1 – View of hole in left horizontal stabilizer (Photo courtesy of the Department of Interior)



Photo 2 – View of damaged left horizontal stabilizer tube (Photo courtesy of the Department of Interior)