



**Photo 1 – View of damaged left wing lift strut (Photo courtesy of the FAA)**



**Photo 2 – View of damaged right aileron (Photo courtesy of the FAA)**