



Photo 1 – View of damage to the left wing tube that was removed from the airframe (Courtesy of Operator)