



Photo 1 – View of inverted airplane and wing and empennage damage (Photo courtesy of the FAA)