



Photo 1 – View of damaged pole and separated right wing tip (Photo courtesy of the FAA)



Photo 2 – View of damaged wings, fuselage, and empennage (Photo courtesy of the FAA)