



Photo 1 – View of damage to the landing gear attachment points (Courtesy of FAA)