



**Photo 1 – View of damaged left wing lift strut (Photo courtesy of the pilot)**