



Photo 1 – View of damage to the tail rotor drive shaft and gear box (Courtesy of FAA)