



Photo 1 – View of damaged tailcone (courtesy of the repair station)



Photo 2 – View of damaged right wing (courtesy of the repair station)