



Photo 1 – View of damage to the wing walk (Courtesy of FAA)



Photo 2 – View of damage to the right main landing gear attachment mount and composite structure -Image was taken with the tail of the airplane to the right (Courtesy of FAA)



Photo 3 - View of damage to the right main landing gear attachment mount and airframe structure -Image was taken looking toward the tail of airplane (Courtesy of FAA)