



Photo 1 – View of damaged right wing lift strut (Photo courtesy of Airport Operations)



Photo 2 – View of damaged vertical stabilizer and rudder (Photo courtesy of Airport Operations)