



Photo 1 – View of damage to the right wing (Courtesy of FAA)



Photo 2 – View of damage to the left wing (Courtesy of FAA)



Photo 3 – View of damage to the right side empennage longeron (Courtesy of FAA)