



Photo 1 – View of engine mount damage (photo courtesy of the FAA)