



Photo 1 – View of damaged left wing and empennage (Photo courtesy of the FAA)