



Photo 1 - View of airplane inverted with damage to the right **wing** lift strut and empennage (Photo courtesy of unknown)