



Photo 1 – View of damaged empennage without vertical stabilizer and rudder (Photo courtesy of the pilot)



Photo 2 – View of damaged empennage from rear (Photo courtesy of the pilot)



Photo 3 – View of damaged empennage (Photo courtesy of the pilot)