



Photo 1 – View of inverted airplane with damaged left wing lift strut and empennage (Photo courtesy of unknown)