




Photo 1 – View of damaged firewall and engine mount frame (courtesy of the airframe and powerplant mechanic)



Photo 2 – View of damage to firewall and nose landing gear tunnel (courtesy of the airframe and powerplant mechanic)