



Picture 1 – View of inverted airplane with damaged empennage (Photo courtesy of the FAA)