



Photo 1 – View of damage to the left main landing gear attachment point (Courtesy of FAA)