



Photo 1 – View of damaged fuselage from underneath (Photo courtesy of the FAA)



Photo 2 – View of landing gear position observation mirror on right wing (Photo courtesy of the FAA)



Photo 3 – View of gear warning microswitch at throttle idle position with visible gap (Photo courtesy of the FAA)