



**Photo 1 – View facing toward the tail of damage to the aft left wing attachment points (Courtesy of FAA)**