



Photo 1 – View of damage to the rudder (Courtesy of FAA)



Photo 2 – View of the rudder horns still attached while the airplane is inverted (Courtesy of FAA)