



Photo 1 – View of horizontal crack to left lower wing spar (courtesy of the FAA)