



Photo 1 – View of damaged left wing lift strut and rudder (courtesy of the FAA)