



Photo 1 – View of inverted airplane with damaged right wing lift strut and empennage (Photo courtesy unknown)