



Photo 1 – View of left wing lift strut damage (photo courtesy of the pilot)