



Photo 1 – View of damaged tailboom (Photo courtesy of the FAA)



Photo 2 – View of damaged transmission mounts (Photo courtesy of the FAA)