




Photo 1 – View of damaged engine mount (courtesy of the FAA)