



Photo 1 – View of fuselage and wing lift strut damage (photo courtesy of the FAA)