



Photo 1 – View of empennage damage (Photo courtesy of the FAA)



Photo 2 – View of fuselage damage from underneath (Photo courtesy of the FAA)