



Photo 1 – View of damage to the left wing lift strut (Courtesy of Operator)