



**Photo – View of damage to main & tail rotor systems, empennage and fuselage (courtesy of the operator)**