



Photo 1 – View of right wing damage (photo courtesy of the FAA)



Photo 2 - View of engine mount damage (photo courtesy of the FAA)