



Photo 1 – View of damaged right-wing I-strut (courtesy of the pilot)