



Photo 1 – View of damaged and separated tailcone (courtesy of the pilot)