



Photo 1 – View of engine mount damage (Photo courtesy of the FAA)