



Photo 1 – View of damaged right wing lift struts (courtesy of the pilot)



Photo 2 – View of damaged rudder (courtesy of the pilot)