



Photo 1 – View of impact markings on engineered material arrestor system (Photo courtesy of the FAA)



Photo 2 – View of damaged fuselage (Photo courtesy of the FAA)