



Photo 1 – View of right wing lift strut damage (photo courtesy of the FAA)



Photo 2 - View of rudder damage (photo courtesy of the FAA)