



Photo 1 – View of damaged right-wing lift strut and empennage (courtesy of the FAA)