



Photo 1 – View of right wing lift strut damage (photo courtesy of the pilot)