



Photo 1 – View of damaged engine mount (Photo courtesy of the FAA)