



Photo – View of damaged engine mount and truss (courtesy of the FAA)