



Photo 1 – View of lower left wing damage (photo courtesy of the FAA)



Photo 2 - View of rudder damage (photo courtesy of the FAA)